

## Double Lock EZr™ Gooseneck Hitches

Make / Model	Style	Years	Capacity	EZr Kit #	Footnotes	Hitch #	Bracket #
<b>Chevrolet</b>							
Silverado 2500	Excluding Cab & Chassis	01 - 04	30,000 LB	60681	Z	60619	60648
Silverado 2500 HD	--	20 - 26	25,000 LB	60690	Z	60611	60701
	Excluding Cab & Chassis	11 - 19	30,000 LB	60680	1, Z	60611	60624
		01 - 10	30,000 LB	60681	Z	60619	60648
Silverado 2500 HD Classic	Excluding Cab & Chassis	07 - 07	30,000 LB	60681	Z	60619	60648
Silverado 3500	Excluding Cab & Chassis	01 - 06	30,000 LB	60681	Z	60619	60648
Silverado 3500 Classic	Excluding Cab & Chassis	07 - 07	30,000 LB	60681	Z	60619	60648
Silverado 3500 HD	Excluding Cab & Chassis	20 - 26	25,000 LB	60690	Z	60611	60701
		11 - 19	30,000 LB	60680	1, Z	60611	60624
		08 - 10	30,000 LB	60681	Z	60619	60648
<b>Dodge</b>							
Ram 2500	Excluding Cab & Chassis	03 - 10	30,000 LB	60682	1, 2, 3, Z	60619	60660
Ram 3500	Excluding Cab & Chassis	03 - 10	30,000 LB	60682	1, 2, 3, Z	60619	60660
<b>Ford</b>							
F-250	--	99 - 99	30,000 LB	60685	Z	60619	60647
F-250 Super Duty	--	11 - 16	30,000 LB	60683	Z	60619	60645
		99 - 10	30,000 LB	60685	Z	60619	60647
F-350 Super Duty	Excluding Cab & Chassis	11 - 16	30,000 LB	60683	Z	60619	60645
		99 - 10	30,000 LB	60685	Z	60619	60647
<b>GMC</b>							
Sierra 2500	Excluding Cab & Chassis	01 - 04	30,000 LB	60681	Z	60619	60648
Sierra 2500 HD	--	20 - 26	25,000 LB	60690	Z	60611	60701
	Excluding Cab & Chassis	11 - 19	30,000 LB	60680	1, Z	60611	60624
		01 - 10	30,000 LB	60681	Z	60619	60648
Sierra 2500 HD Classic	Excluding Cab & Chassis	07 - 07	30,000 LB	60681	Z	60619	60648
Sierra 3500	Excluding Cab & Chassis	01 - 06	30,000 LB	60681	Z	60619	60648
Sierra 3500 Classic	Excluding Cab & Chassis	07 - 07	30,000 LB	60681	Z	60619	60648
Sierra 3500 HD	Excluding Cab & Chassis	20 - 26	25,000 LB	60690	Z	60611	60701
		11 - 19	30,000 LB	60680	1, Z	60611	60624
		07 - 10	30,000 LB	60681	Z	60619	60648
<b>Ram</b>							
2500	--	11 - 13	30,000 LB	60682	1, 2, 3, Z	60619	60660
3500	Excluding Cab & Chassis	11 - 12	30,000 LB	60682	1, 2, 3, Z	60619	60660

### Footnotes

1- Passenger-side wheel well flange must be bent for frame rail access

2- Check inverted ball clearance with heavy loads on two-wheel drive

3- Exhaust may have to be permanently lowered on power wagon and Mega cab applications

Z- No frame drilling required

All Models: Brake, fuel, and electrical lines may need to be loosened or repositioned. Heat shield requires modification or removal

\* Continued while supplies last